

## DATA SHEET

# PST



## Manostats



Range from  $\pm 100$  Pa to  $\pm 2000$  mbar (according to model)



Visual and audible alarm, red led in front



### Features

- RCR relay output 3A/240 Vac (NC), power supply 24 Vac/Vdc
- ABS V0 IP65 housing
- "1/4 turn" system mounting with wall-mount plate
- Housing with simplified mounting system
- Solenoid valve for auto-calibration (only on PST11 model)

### Measured parameter

Parameter	Accuracies*	Measuring ranges	Resolution
Pressure	PST-11: $\pm 1\%$ of reading $\pm 2$ Pa PST-12: $\pm 1.5\%$ of reading $\pm 3$ Pa PST-13: $\pm 1.5\%$ of reading $\pm 3$ mmH <sub>2</sub> O PST-14 and PST-15: $\pm 1.5\%$ of reading $\pm 3$ mbar	From -100/+100 Pa to -2000/+2000 mbar (according to model)	PST-11, PST-12 and PST-13: 1 Pa, 0.1 mmH <sub>2</sub> O, 0.01 inWG, 0.01 mmHG, 0.1 daPa, 0.001 kPa (0.01 kPa pour le PST-13), 0.01 hPa, 0.01 mbar PST-14 and PST-15 : 1 mbar, 0.1 inWG, 1 mmHG, 0.1 PSI, 1 mmH <sub>2</sub> O, 1 daPa, 1 hPa, 0.1 kPa

### Part number

PST	-	<table border="1"> <tr> <td>Measuring range</td> <td>13: -10 000/+10 000 Pa</td> </tr> <tr> <td>11: -100/+100 Pa</td> <td>14: -500/+500 mbar</td> </tr> <tr> <td>12: -1000/+1000 Pa</td> <td>15: -2000/+2000 mbar</td> </tr> </table>	Measuring range	13: -10 000/+10 000 Pa	11: -100/+100 Pa	14: -500/+500 mbar	12: -1000/+1000 Pa	15: -2000/+2000 mbar	<b>Example: PST – 13</b> Manostat PST with measuring range from -10000 to +10000 Pa
Measuring range	13: -10 000/+10 000 Pa								
11: -100/+100 Pa	14: -500/+500 mbar								
12: -1000/+1000 Pa	15: -2000/+2000 mbar								


### Technical specifications

Output	1 RCR relay. NO (normally opened): 5A / NC (normally closed): 3A / 240 Vac. Common mode voltage <30 Vac
Alimentation Power supply	24 Vac/Vdc $\pm 10\%$
Consommation	3 VA
Relay and alarm status	Red led in front and internal buzzer (70 dB at 10 cm)
European directives	2014/30/EU EMC; 2014/35/EU Low Voltage; 2011/65/EU RoHS II; 2012/19/EU WEEE
Electrical connection	Terminal block for cables $\emptyset 0.05$ to 2.5 mm <sup>2</sup> . Carried out according to the code of good practice
PC communication	USB-mini Din cable
Environment	Air and neutral gases

\*All the accuracies indicated in this technical datasheet were stated in laboratory conditions, and can be guaranteed for measurements carried out in the same conditions, or carried out with calibration compensation.



- **Threshold configuration**

The button  allows to activate or not an alarm (threshold), to set the action of the alarm (edge), to set the threshold(s) value, to set the time-delay and to acknowledge the alarm.

**Working principle:**

- By pressing on the button more than 3 seconds, you can validate the setting and go to the next setting.
- By pressing quickly on the button, you can increment a value and scroll down the different option or values.

- **Activate or deactivate an alarm**

- Press the button for 3 seconds, "CONF" is displayed then "NEG", meaning that the relay is in negative security, it is excited during an alarm condition.

If needed, press quickly on the button to switch the relay in positive security, the relay is de-energized during an alarm condition or a current breaking, "POS" is displayed.

- Press 3 s the button, "Buzz" screen is displayed with "ON" or "OFF" blinking. Briefly press on the button to activate ("ON") or deactivate ("OFF") (according to the last saved configuration) the buzzer during an alarm condition.


- Press 3 s the button, "Alarm" screen is displayed with "On" or "Off" blinking (according to the last saved configuration).

- Press quickly the button, the display changes from "On" (activated alarm) to "Off" (deactivated alarm).


- Press 3 seconds the button to confirm the setting. If the alarm is deactivated, the instrument displays the measurement; if the alarm is activated, the instrument displays the following setting.

- **Set the action of the alarm (rising edge or falling edge)**


The edge determines the action of the alarm according to the trespassing direction of the threshold(s).




Rising edge (1 threshold): the alarm goes off when the measurement exceeds the threshold and stops when it is below the threshold.



Falling edge (1 threshold): the alarm goes off when the measurement is below the threshold and stops when it exceeds the threshold.




Monitoring (2 thresholds): the alarm goes off when the measurement is outside the defined low and high thresholds.




Measurement (m) > Threshold (S) during the time-delay T1: Alarm activation.

Measurement (m) < Threshold (S) - Hysteresis (H) during the time-delay T2: Alarm deactivation.



Measurement (m) < Threshold (S) during the time-delay T1: Alarm activation.

Measurement (m) > Threshold (S) + Hysteresis (H) during time-delay T2: Alarm deactivation.



The alarm goes off when the measurement is outside the low and high thresholds.

- Press briefly the button to select the trespassing direction then press the button more than 3 seconds to validate this direction and set the thresholds.

- **Set the threshold(s) value**

The first digit blinks, it corresponds to the positive (0) or negative (-) setting of the threshold value. Press briefly on the button to select the sign for the threshold value. Press on the button more than 3 seconds to validate.

The second digit blinks, press briefly on the button to scroll the numbers. Press the button more than 3 seconds to validate.

Repeat the process until the last digit to configure the threshold value, validate the threshold and go to the following setting.

If the monitoring edge has been selected, the transmitter displays the setting of the second threshold.

- **Set the hysteresis**

The hysteresis is only for the rising edge and the falling edge modes.

In rising edge mode, the hysteresis allows to the transmitter to stay in alarm when the measurement is between the threshold and the threshold minus the hysteresis.

Ex: for a 100 Pa threshold and a 10 Pa hysteresis, the instrument will stay in alarm when the measurement will be between 100 and 90 Pa. In falling edge mode, the hysteresis allows to the transmitter to stay in alarm when the measurement is between the threshold and the threshold plus the hysteresis.

Ex: for a 100 Pa threshold and a 10 Pa hysteresis, the instrument will stay in alarm when the measurement will be between 100 and 110 Pa. The first digit blinks, set it pressing the button briefly several times then press on the button more than 3 seconds to set the following digit.

Once the hysteresis is set, press the button more than 3 seconds to validate and set the time-delays.

